



Photo 1 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Leachate going into a drainage ditch.



Photo 2 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Vegetated drainage ditch next to the asphalt silage pad.



Photo 3 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
View of field that receives runoff from the silage pad, bordering an unnamed stream.



Photo 4 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Spoiled feed pile (forefront) next to a storage bay on the old silage pad.



Photo 5 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Evidence of runoff from the old silage pad toward the roadside ditch on Silver Lake Rd.




Photo 6 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
View of roadside ditch along Silver Lake Rd. (looking southwest).



Photo 7 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16

Low trough collecting leachate and water between the main barn and an old silage bunker.



Photo 8 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Leachate emanating from the old silage bunker in photo #7.



Photo 9 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Discharge pipe for the low trough area depicted in photos #7-8.



Photo 10 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Sloped field with some erosion, receives discharge from the area in photos #7-9.



Photo 11 – Mountain View Dairy, Silver Lake Rd., Georgia, VT – 06/23/16
Cow crossing over/through unnamed stream #1 in the dry cow pasture.